

कार्यालय कार्यपालन यंत्री  
लोक निर्माण विभाग (भ./स.)संभाग क्र.1 रीवा (म.प्र.)

Web site :www.mp.gov.in/pwmp

email :-eepwd 1 [rewa@mp.nic.in](mailto:rewa@mp.nic.in)

Phone No.07662-256858

पत्र क्र.....4905/तक./2024-25

रीवा,दिनांक 7/10/2024

प्रति,

✓  
प्राचार्य,  
डी पॉल स्कूल  
मैदानी, तहसील, हुजूर जिला-रीवा (म.प्र.)

विषय :- भवन का सुरक्षा प्रमाण पत्र बावत।

संदर्भ :- आपका पत्र प्राप्त दिनांक 12/09/2024

उपरोक्त विषयांतर्गत संदर्भित पत्र के तारतम्य में डी पॉल स्कूल मैदानी, तहसील हुजूर जिला-रीवा (म.प्र.) भवन का सुरक्षा संबंधी प्रमाण पत्र प्रदाय हेतु अनुविभागीय अधिकारी लोक निर्माण विभाग (भ./स.) उपसंभाग क्र.1 रीवा एवं उपयंत्री द्वारा दिनांक 23/09/2024 को संयुक्त रूप से विषयांकित भवन का सुरक्षा संबंधी निरीक्षण कर प्रतिवेदन इस कार्यालय को पत्र क्र 642/तक./2024 रीवा, दिनांक 23/09/2024 द्वारा प्राप्त हुआ है।

अतः अनुविभागीय अधिकारी से प्राप्त भवन सुरक्षा प्रमाण पत्र प्रति हस्ताक्षरित कर आपकी ओर अग्रेषित है।

सहपत्र :-भवन का सुरक्षा प्रमाण पत्र।

कार्यपालन यंत्री  
लोक निर्माण विभाग(भ./स.)  
संभाग क्र.1रीवा(म.प्र.)

**OFFICE OF THE EXECUTIVE ENGINEER P.W.D. (B./R.) DIVISION NO.1  
REWA (M.P.)**

Website: [www.mp.gov.in/pwdmp](http://www.mp.gov.in/pwdmp)

E- mail- eepwd 1 [rewa@mp.nic.in](mailto:rewa@mp.nic.in)

Phone – 07662 -256858

**FITNESS CERTIFICATE**

To be filled by the Inspecting Officer

1. Name of the officer : M.K. Dwivedi Divisional Officer P.W.D. (B./R.) Division NO.1 Rewa (M.P.)
2. Name of the School : D E PAUL SCHOOL REWA( M.P.)
3. Location with name of education District/Sub. District: Maidani, Tehsill Huzur, Rewa,( M.P.)
4. Classification of Building as specified in column 4 of the application for fitness certificate and size:  
(I) 867.843 sqm. Built Up Area (Year-2012)  
(II) 532.157 sqm. Built Up Area (Year-2016)
- 5- Period for which the certificate is issued :2024-25
- 6- nature of defects, if any :  


a ) Foundation and basement:	Not Applicable
b ) Superstructure:	Not Applicable
c ) Doors and windows:	Not Applicable
d ) Wood work wrought and put up :	Not Applicable
e ) Roof :	Not Applicable
f ) Flooring :	Not Applicable
g ) Miscellaneous (Cracks, etc.):	Not Applicable
- 7- any major defects noticed which will render the building unsafe in any manner : No
- 8- Whether maintenance works have been done properly : Yes
- 9- whether the structure is sound or not for conducting classes : Building is sound and safe  
Note: 1. the stability of the structure should be examined also with reference to location. altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

**CERTIFICATE**

Certified that the school building was inspected by me on 23/9/2024 and found to be fit to conduct classes, for the period 2024-25 for the reasons stated above.


Place : Rewa


Date : 23/9/2024

  
Sub Divisional Officer  
P. W. D. (B./R.) Sub Division No. 1  
Rewa (M. P.)

Entd. No 4905 /TS/2024-25

Copy forwarded to:- Principal, D E PAUL SCHOOL Maidani, Tehsill Huzur, , Rewa,( M.P.)

  
EXECUTIVE ENGINEER  
P.W.D.(B./R.) DIVISION NO.1  
REWA (M.P.)  
Rewa Dated 7-10-2024

  
EXECUTIVE ENGINEER  
P.W.D.(B./R.) DIVISION NO. 1  
REWA (M.P.)